




亏.2





	TEMPERATURE (°C)	TIME (SECOND)	HEATING MODE
1 2 3 4 5	150 250 1000 1000 2300 2500	20 10 10 10 2 2	RUMP RUMP RUMP STEP STEP STEP

(PRIOR ART)



Fy.6 (PRIOR ART)